


## Attachment 4



**Image 1:** Base issues beneath the playing surface, causing inaccuracies and tracking problems during bowls games.




**Image 2:** This shows the crumbling base, which should consist of a bonded mixture of blue metal and concrete to create a solid, level playing surface.



**Image 3:** This depicts the removal of the crumbling base. It should have been a bonded mixture of blue metal and concrete to provide a solid, level playing surface.



**Image 4:** This image highlights sub-base variations of up to 30mm in certain areas, far exceeding the accepted tolerance of  $\pm 4\text{mm}$ . These discrepancies were a major factor in the failure of the base system.



**Image 5:** This image shows the amelioration works being carried out to level the sub-base, preparing it for the installation of the new base system.